



# WEST VALLEY REGIONAL FIRE TRAINING



## TRAINING PLAN

Subject		RMS Training Code
<b>Apparatus Checkout</b>		<b>05-D-01</b>
Instructors		
<u>A</u>	<u>B</u>	<u>C</u>
Logistics		
<u>Time Required</u> 2 hrs	<u>Equipment Needed</u>	

### DESCRIPTION

#### Objectives:

1. Identify the standards and requirements of a DOT Pre-Trip Inspection
2. Demonstrate the proper sequence for conducting an Apparatus Check-Out / Pre-Trip Inspection
3. Perform a proper Pre-Trip Inspection and become familiar with new Apparatus or Assignment

#### Description / Outline:

The relevant course materials and PowerPoint presentations may be found on Fire Department Computers <F:/Fire/Training/TrainingFolders/DriverOperator/ApparatusCheckout>  
Or attached to the Training Plan as supporting Documents

1. Present and discuss the DOT requirements and recognitions for conducting a DOT Pre-Trip Inspection
  - C-O-L-A PowerPoint
  - Tire Inspection PowerPoint
  - WSFD Apparatus Checkout Sheet / Procedures for Engine/Truck/Brush
2. Demonstrate a recommended sequence for conducting an Apparatus Checkout / Pre-Trip Inspection
  - New Driver/Operators, or Driver/Operators assigned to a new piece of equipment will have an opportunity to become familiar with the equipment they are responsible for.

Prepared By:

Date / Date Revised:

JAN. 2020